

SPECIAL SERVICE INSTRUCTION

SSI008

Compliance Will Enhance Safety

SUBJECT: Replacement of PMA Roller Lifter (P/N AEL23381)

PURPOSE: To provide replacement PMA roller lifters (P/N AEL23381) purchased by customers between July 2017 and March 2018; to explain the warranty policy guidelines.

COMPLIANCE: CMI recommends replacement of PMA roller lifters (P/N AEL23381), purchased by customers for serviceable spares or that were installed for engine repair or overhaul between July 2017 and March 2018; not to exceed 3 years from the date of this Service Document or 500 operating hours after installation, whichever occurs first.

MODELS

AFFECTED: As installed by customers who purchased CMI PMA roller lifters (P/N AEL23381) from authorized Continental Motor’s distributors. Affected overhaul applications are limited and based on direct customer notification via this Special Service Instruction (SSI008).

SPECIAL SERVICE INSTRUCTIONS

ARE DISTRIBUTED DIRECTLY

TO THE AFFECTED ENGINE OWNERS

AS LISTED ABOVE AND ARE NOT PART OF THE

PUBLISHED

SERVICE DOCUMENT SET.

IF YOU ARE AN AFFECTED ENGINE OWNER OR

WANT FURTHER DETAILS, PLEASE CONTACT

CMI CUSTOMER SERVICE AT:

1-251-436-8299

1-888-826-5465.

ISSUED	REVISED	 P.O. Box 90 Mobile, AL 251-436-8299	PAGE NO	DOC NO	REVISION
2018/04/30			1 of 2	SSI008	

Intentionally Left Blank

ISSUED	REVISED		PAGE NO	DOC NO	REVISION
2018/04/30		P.O. Box 90 Mobile, AL 251-436-8299	2 of 2	SSI008	