

SPECIAL SERVICE INSTRUCTION

Compliance Will Enhance Safety

SUBJECT: Crankcase Inspection, VA540A71N

PURPOSE: To issue instructions for recurring crankcase inspections on the specified experimental engine.

COMPLIANCE: See document contents

MODELS

AFFECTED: Experimental VA540A71N engine crankcases, as listed in Table 1 (reference Service Document).

**SPECIAL SERVICE INSTRUCTIONS
ARE DISTRIBUTED DIRECTLY
TO THE AFFECTED ENGINE OWNERS
AS LISTED ABOVE AND ARE NOT PART OF THE
PUBLISHED
SERVICE DOCUMENT SET.
IF YOU ARE AN AFFECTED ENGINE OWNER OR
WANT FURTHER DETAILS, PLEASE CONTACT
CMI CUSTOMER SERVICE AT:
1-251-436-8299
1-888-826-5465.**

ISSUED	REVISED		PAGE NO	DOC NO	REVISION
2017/12/29		P.O. Box 90 Mobile, AL 251-436-8299	1 of 2	E-SSI001	

Intentionally Left Blank

ISSUED	REVISED		PAGE NO	DOC NO	REVISION
2017/12/29		P.O. Box 90 Mobile, AL 251-436-8299	2 of 2	E-SSI001	